


Fig. 3



099955678 112901

Fig.4




Fig.5




Fig. 6





Fig. 7



0995678-1294
T062T 8295660

Fig. 8




Fig. 9A




Fig. 9B




Fig.10A




Fig.10B




Fig.10C




Fig.11




Fig.12A




Fig. 12B





Fig. 13



0995679-1-1901
 0521 5495550

Fig.14




Fig. 15





Fig.16



0995678.112901

Fig. 17




Fig. 18




Fig. 19





Fig. 20

Influence on Outer Race Inner Surface



T0627T" S2956650